SP 659

Only typed forms are accepted. Please send an electronic copy of the completed form.

If you need assistance completing the form, please contact Michael Houser, State Architectural Historian, at 360-586-3076 or Michael houser@dahp.wa.gov

| Washington State   | Far   |
|--|-------|
| HERITAGE BARN  | Lar   |
| REGISTER   |       |
|  | His   |
|  | Allic |
|  | Own   |
|  | Larry |
|  | Phor  |
|  | Ema   |
| The second secon | Emi   |

| Farm Name                   | Property Location Address: 9003 N. Garfield Rd. |  |  |  |  |
|-----------------------------|---|--|--|--|--|
| Larry and Bonnie Busse Farm |   |  |  |  |  |
|                             | City: Spokane Zip: 99224                        |  |  |  |  |
| Historic Name               | County  |  |  |  |  |
| Allice, Henry, Farm         | Spokane   |  |  |  |  |
| Owners Name                 | Owner Address                                   |  |  |  |  |
| Larry and Bonnie Busse      | Address:9003 N. Garfield Rd.                    |  |  |  |  |
|                             | City: Spokane                                   |  |  |  |  |
| Phone: (509) 466 4501       | State: WA                                       |  |  |  |  |
| Email: larbon@ptera.net     | Zip: 99224                                      |  |  |  |  |

| BARN   | ROOF SHAPE  | ROOF<br>COVERING                                      | FLOOR PLAN  | SIDING  | FOUNDATION<br>MATERIAL                           | PAINTING/<br>DECORATION   | OTHER BARN<br>FEATURES   |
|--|---|---|---|---|--|---|--|
| Good Fair Poor Altered Ruins  BARN BUILT DATE: | Gable Broken Gable Gambrel Hip Gothic Monitor Round Dutch Conical Other | Asphalt Metal Wood Other  CURRENT USE Ag Vacant Other | Square Rectangular Round Irregular L- Shape T- Shape Size: 40' x 60'  Height: 30-40 ft. | ☐ Metal ☐ Wood – Horizontal ☐ Wood – Board & Batten ☑ Wood Vertical ☐ Concrete ☐ Brick ☐ Stone ☐ Asbestos ☐ Other | ☐ Concrete ☐ Stone ☐ Brick ☐ Wood ☐ None ☐ Other | Painted?  No Yes Color: red and white  Names/Dates/ Decoration?  No Yes Describe: | ☐ Cupola ☐ Dormer ☐ Hay Hood ☐ Ventilator ☐ Weather Vane ☐ Lightning Rod ☐ Silo ☐ Milking Shed ☐ Other |

\* PROPERTY HISTORY: (Expand on the history of the barn/property such as use, original owner, builder, architect, family stories and memories, etc.. add additional pages if necessary)

Henry Allice homesteded our place in the 1880's. He and his dad cut the trees on the place, let them age a year and had them cut into lumber. A barn raising crew framed the barn using notches and pegs. Henry lived in the barn while other logs were drying, so he could build the house.

Please provide <u>current</u> photos of nominated property (interior and exterior (all four sides)) and a map indicating the location of property in relationship to major roads. Digital images are preferred (please provide disc) or print on photographic paper.

barn. Include an arrow pointing north for directional purposes.


OTHER EXPMETEAD

Only typed forms are accepted. Please send an electronic copy of the completed form.

If you need assistance completing the form, please contact Michael Houser, State Architectural Historian, at 360-586-3076 or <a href="Michael.houser@dahp.wa.gov">Michael.houser@dahp.wa.gov</a>.


| BUILDINGS  |                                     | If building does not exist, please check N/A box Provide additional photos of secondary buildings/structures regardless of age. |   |            |                        |  |                |
|--|-------------------------------------|---|---|------------|------------------------|--|----------------|
|  | ROOF<br>SHAPE<br>(Gable, Hip, etc.) | ROOF<br>COVERING  | FLOOR PLAN<br>(Square, L-Shape,<br>Rectangular, etc.) | SIDING     | FOUNDATION<br>MATERIAL | OTHER FEATURES:<br>(Style, Color, Trim, etc) | BUILT DATE     |
| DWELLING  ☐ Good ☑ Fair ☐ Poor ☐ Altered ☐ Ruins ☐ N/A     | gable                               | asphalt   | square  | wood       | rock                   |  | early 1900's   |
| OUTHOUSE  Good Fair Poor Altered Ruins N/A                 |                                     |   |   |            |                        |  |                |
| CHICKEN COOP  ☐ Good ☐ Fair ☐ Poor ☐ Altered ☐ Ruins ☒ N/A |                                     |   |   |            |                        |  |                |
| MACHINE SHED  ☐ Good ☑ Fair ☐ Poor ☐ Altered ☐ Ruins ☐ N/A | gable                               | metal   | rectangle   | wood       | cement                 |  | 1950           |
| MILK HOUSE  Good Fair Poor Altered Ruins N/A               | gable                               | metall  | rectangle   | block      | cement                 |  | 1950           |
| SILO  Good Sair Poor Altered Ruins N/A                     | dome                                | metal   | round   | block      | dirt                   |  | 1950           |
| OTHER:  Good Fair  Poor Altered Ruins N/A                  |                                     |   |   |            |                        |  |                |
| OTHER:  Good Fair  Poor Altered Ruins N/A                  |                                     |   |   |            |                        |  |                |
| Please provide a   | sketch of t                         | he farmste  | ad lavout ind   | icating th | e location of o        | other buildings in re                        | elation to the |

Return form and additional documentation to: DAHP 1063 S. Capitol Way, Suite 106 Olympia, WA 98504



Henry Allice Farmstead 9003 N. Garfield Rd. Spokane, WA 99224





Farm Service Agency Spokane-Pend Oreille County

Farm: 335 Tract: 305

**Operator Larry Busse** 

1 In equals 495 Ft

1,280

March 18 J09

Wetland identifiers do not represent the size, shall Refer to your original determination (CPA-026 and attached maps). exact wetalnd boundaries and labels, or contact NRCS

specific determinations of the area.

Field Boundaries

Wetland Determination Ider













Larry Busse 9003 N. Garfield Rd. Spokane, WA 99224 (509)466-4501


East view of barn



North view of barn



West view of barn



Larry Busse 9003 N. Garfield Spokane, WA (509)466-4501

South (front) view of barn

Pegged and notched beams.
No nails were used when barn was framed.