Only typed forms are accepted. Please send an electronic copy of the completed form.

If you need assistance completing the form, please contact Michael Houser, State Architectural Historian, at 360-586-3076 or Michael houser@dahp.wa.gov.

	<u> </u>
Washington State	
HERITAGE BARN	
REGISTER A	
	\06 ° \$
The second of th	
The second secon	SEC.
	疆
	The state of the s
0	المنفاء بالمجاور عوالا
The second secon	

Farm Name	Property Location				
Long Barn Farm	Address: 1902 So. Glenrose Rd.				
	City: Spokane Zip: 99223-1016				
Historic Name	County				
Champion Barn	Spokane				
Owners Name	Owner Address				
Ellen Gay Schroff	Address: 1902 S. Glenrose Rd.				
	City: Spokane				
Phone: 509-534-6060	State: WA				
Email: schroffegay@msn.com	Zip: 99223-1016				

BARN	ROOF SHAPE	ROOF COVERING	FLOOR PLAN	SIDING	FOUNDATION MATERIAL	PAINTING/ DECORATION	OTHER BARN FEATURES
CONDITION Good Fair Poor Altered Ruins BARN BUILT DATE: c 1903	Gable Broken Gable Gambrel Hip Gothic Monitor Round Dutch Conical		☐ Square ☐ Rectangular ☐ Round ☐ Irregular ☐ L- Shape ☐ T- Shape Size: 160'x36' Height: 25'	☐ Metal ☐ Wood – Horizontal ☐ Wood – Board & Batten ☐ Wood Vertical ☐ Concrete ☐ Brick ☐ Stone ☐ Asbestos ☐ Other	☐ Concrete☐ Stone☐ Brick☐ Wood☐ None☐ Other	Painted? No Yes Color: red w/white trim Names/Dates/ Decoration? No Yes Describe: "1929" insribed in concrete	☐ Cupola ☐ Dormer ☐ Hay Hood ☐ Ventilator ☐ Weather Vane ☐ Lightning Rod ☐ Silo ☑ Milking Shed ☑ Other work shed

* PROPERTY HISTORY: (Expand on the history of the barn/property such as use, original owner, builder, architect, family stories and memories, etc.. add additional pages if necessary)

Built in 1903 along with farmhouse. Operated as a dairy farm by family named Champion until the late 1920's. Owned by family named Frye and operated as Glenrose Dairy in the 1930's. I have a picture of the place along with the Glenrose Dairy trucks dated 1932. The picture is taken from the top of the hill with the barn in the foreground, so you can clearly see the original structure, along with part of the dairy herd. Stayed as a dairy farm until converted to a chicken and egg farm in the late 1950's or early 1960's. Purchased by W. Salsbury and used as a base for his geological survey business. Purchased by C. McIver and used to raise beef cattle and horses until 1998 when I purchased the place.

I installed a white post and rail fence and maintain Arabian horses on the property at present. Interior still has the original wood flooring in the milking stall area and in the west end of the barn which I use as shelter for the horses. Hay is now stored in the east end of the barn.

Construction of the barn is similar to old barns I viewed in upper New York State last year; a type A-frame with the roof resting on the sides of the squared off

Only typed forms are accepted. Please send	an electronic copy of the completed form.
--	---

orchards.

If you need assistance completing the form, please contact Michael Houser, State Architectural Historian, at 360-586-3076 or Michael.houser@dahp.wa.gov. "A". Some of the interior wood has been scavenged, but it is 90% original.

The property is located on the South Hill facing north onto 17th (Glenrose) at the corner of Big Springs and Glenrose. It is approximately 1 and 1/2 blocks east of Havana-Yale Street, the city limits. It is at the extreme north end of Glenrose Prairie and is just west of Cherry Lane which used to have many cherry

Please provide <u>current</u> photos of nominated property (interior and exterior (all four sides)) and a map indicating the location of property in relationship to major roads. Digital images are preferred (please provide disc) or print on photographic paper.

OTHER FARMSTEAD BUILDINGS		If building does not exist, please check N/A box Provide additional photos of secondary buildings/structures regardless of age.					
	ROOF SHAPE (Gable, Hip, etc.)	ROOF COVERING	FLOOR PLAN (Square, L-Shape, Rectangular, etc.)	SIDING	FOUNDATION MATERIAL	OTHER FEATURES: (Style, Color, Trim, etc)	BUILT DATE
DWELLING ☑ Good ☐ Fair ☐ Poor ☐ Altered ☐ Ruins ☐ N/A	Four gabled cross with shed roofs	Asphalt	4 Bdr, 2 B, Fmlyrm, Lrm, Den, Frplc	Original Dutch lap, wood	Stacked stone	white w/green trim	1903
OUTHOUSE Good Fair Poor Altered Ruins N/A							
CHICKEN COOP Good Fair Poor Attered Ruins N/A							
MACHINE SHED ☐ Good ☐ Fair ☐ Poor ☐ Altered ☐ Ruins ☐ N/A	Shed w/ clerestory windows	Asphalt	Rectangular	Wood, Dutch lap	Cement	Red and white trim	1940's
MILK HOUSE Sood Fair Poor Altered Ruins N/A	Shed w/clerestory windows	Asphalt	Rectangular, two rooms	Wood, Dutch lap	Cement	Red and white trim	1940's
SILO ☐ Good ☐ Fair ☐ Poor ☐ Altered ☐ Ruins ☒ N/A							

Only typed forms are accepted. Please send an electronic copy of the completed form.							
If you need assistance completing the form, please contact Michael Houser, State Architectural Historian, at 360-586-3076 or Michael houser@dahp.wa.gov.							
OTHER: ☐ Good ☐ Fair ☐ Poor ☐ Altered ☐ Ruins ☒ N/A							
OTHER: ☐ Good ☐ Fair ☐ Poor ☐ Altered ☐ Ruins ☒ N/A							
Please provide a sketch of the farmstead layout indicating the location of other buildings in relation to the							
barn. Include an arrow pointing north for directional purposes.							

Return form and additional documentation to: DAHP 1063 S. Capitol Way, Suite 106 Olympia, WA 98504



































