SP 663

Only typed forms are accepted. Please send an electronic copy of the completed form.

If you need assistance completing the form, please contact Michael Houser, State Architectural Historian, at 360-586-3076 or Michael.houser@dahp.wa.gov.

Washington State	Farm Name	Property Location		
HERITAGE BARN	Girvin Barn	Address: 6323 E Jamieson Road		
REGISTER		City: Spokane Zip: 99223		
	Historic Name	County		
		Spokane		
	Owners Name	Owner Address		
	Shaw Girvin Family Partners	Address:4203 S. Perry		
		City: Spokane		
	Phone: 509-624-0314	State: WA		
	Email: girvingw@comcast.net	Zip: 99203		
The second s	53 1			

BARN	ROOF SHAPE	ROOF COVERING	FLOOR PLAN	SIDING	FOUNDATION MATERIAL	PAINTING/ DECORATION	OTHER BARN FEATURES
CONDITION Good Fair Poor Altered Ruins BARN BUILT DATE: 1904	Gable Gable Gable Gambrel Hip Gothic Monitor Round Dutch Conical Other	 Asphalt Metal Wood Other CURRENT USE Ag Vacant Other Storage 	Square Rectangular Round Irregular L- Shape T- Shape Size: 40' x 40'	 Metal Wood – Horizontal Wood – Board & Batten Wood Vertical Concrete Brick Stone Asbestos Other 	 ☐ Concrete ⊠ Stone ☐ Brick ☐ Wood ☐ None ☐ Other 	Painted? No Yes Color: Red Names/Dates/ Decoration? No Yes Describe:	 Cupola Dormer Hay Hood Ventilator Weather Vane Lightning Rod Silo Milking Shed Other 1/2 horse stalls, 1/2 cow stalls on lower level of barn

* PROPERTY HISTORY: (Expand on the history of the barn/property such as use, original owner, builder, architect, family stories and memories, etc.. add additional pages if necessary)


House, machine shed and barn were built in 1904. The main arena in the barn was designed to store hay. Side area was used as a milking station.


Please provide <u>current</u> photos of nominated property (interior and exterior (all four sides)) and a map indicating the location of property in relationship to major roads. Digital images are preferred (please provide disc) or print on photographic paper. Only typed forms are accepted. Please send an electronic copy of the completed form. If you need assistance completing the form, please contact Michael Houser, State Architectural Historian, at 360-586-3076 or Michael.houser@dahp.wa.gov.

OTHER FARMSTEAD BUILDINGS		If building does not exist, please check N/A box Provide additional photos of secondary buildings/structures regardless of age.					
	ROOF SHAPE (Gable, Hip, etc.)	ROOF	FLOOR PLAN (Square, L-Shape, Rectangular, etc.)	SIDING	FOUNDATION MATERIAL	OTHER FEATURES: (Style, Color, Trim, etc)	BUILT DATE
DWELLING Good Gair Poor Altered Ruins N/A	Gable	Asphalt	Square	Wood	Stone	Tan	1904
OUTHOUSE Good Fair Poor Altered Ruins N/A							
CHICKEN COOP		2					
MACHINE SHED Good Good Fair Poor Altered Ruins N/A	Gable	Metal	Rectangular	Wood	Concrete	Red	1920
MILK HOUSE Good Fair Poor Altered Ruins N/A							
SILO Good Grair Poor Altered Ruins N/A							
OTHER: Good Fair Poor Altered Ruins N/A							
OTHER: Good Fair Poor Altered Ruins N/A							

Please provide a sketch of the farmstead layout indicating the location of other buildings in relation to the barn. Include an arrow pointing north for directional purposes.

Return form and additional documentation to: DAHP 1063 S. Capitol Way, Suite 106 Olympia, WA 98504





GIRVIN BAIZN 6323 E. JAMIESON ND SPORASE, WA



