5P 556

Handwritten forms accepted, typed form is preferred. Please send an electronic copy of the completed form.

If you need assistance completing the form, please contact Michael Houser, State Architectural Historian, at 360-586-3076 or Michael houser@dahp.wa.gov.


Washington State				Name		* Property Location			
HERITAGE			Jaclin Farms			Address: 9715 E. Tallman Road			
REGISTER	A		Historic Name Schneider, John M., Barn * Owners Name			City: Chattaroy Zip: 99003 County Spokane * Owner Address			
		692							
			John & Linda Schneider			Address: Same as Above			
	Aue.			Linua Scrineidei		City: State:			
			Phone: (509) 238-6690			Zip:			
				jjsnles@earthlin	k.net				
BARN	ROOF SHAPE	ROOF COVERING	3	FLOOR PLAN	SIDING	FOUNDATION MATERIAL	PAINTING/ DECORATION	OTHER BARN FEATURES	
CONDITION Good Fair Poor Altered Ruins BARN BUILT DATE: 1922	☐ Gable ☐ Gambrel ☐ Gothic ☐ Bow Truss ☐ Monitor ☐ Round ☐ Shed ☐ Conical ☐ Other	mbrel		☐ Square ☐ Rectangular ☐ Round ☐ Irregular ☐ L- Shape ☐ T- Shape Size: 25 x 36 Height: 25'		Concrete Stone Brick Wood None Other	Painted? No Yes Color: Names/Dates/ Decoration? No Yes Describe:	Cupola Dormer Hay Hood Ventilator Weather Vane Lightning Rod Silo Milking Shed Other	
additional page Purchased by	ges if necessary)	chneider in 1	1901, ал	d still owned by m	such as use, builder, a	•			
indicating				-	perty (interior an es are preferred	•	**	•	

Handwritten forms accepted, typed form is preferred. Please send an electronic copy of the completed form.

If you need assistance completing the form, please contact Michael Houser, State Architectural Historian, at 360-586-3076 or Michael.houser@dahp.wa.gov.

OTHER FARM BUILDINGS	ISTEAD	If building does not exist, please check N/A box * Please provide additional digital photos of secondary buildings/structures								
	ROOF SHAPE	ROOF COVERING	FLOOR PLAN	SIDING	FOUNDATION MATERIAL	OTHER FEATURES: (Style, Trim, Color, etc)	BUILT			
DWELLING ☐ Good ☐ Fair ☐ Poor ☐ Altered ☐ Ruins ☐ N/A	Gable	Asphalt		Wood	Concrete	White	1976			
OUTHOUSE Good Fair Poor Altered Ruins N/A										
CHICKEN COOP Good Fair Poor Altered Ruins N/A						-				
MACHINE SHED Good Fair Poor Altered Ruins N/A										
MILK HOUSE Good Sair Poor Altered Ruins N/A	Gable	Metal	Square	Wood	Concrete	12 x 12	1936			
SILO Good Fair Poor Altered Ruins N/A										
OTHER: ☐ Good ☐ Fair ☒ Poor ☐ Altered ☐ Ruins ☒ N/A	Shed	Asphalt	Rectangular	Wood	Concrete	lean-to built on side of barn, used a milking parlor	1936			
OTHER: Good Fair Poor Altered Ruins N/A										
Please provide	a sketch o	f the farmst	ead layout	indicating	g the location	of other buildings in re	 elation			
to the barn. Inc	lude an ai	row pointin	a north for	directiona	al purposes.	_				

Return form and additional documentation to: **DAHP** 1063 S. Capitol Way, Suite 106 Olympia, WA 98504



 \mathcal{N}

E

Hause

RAPIN PARLOR NOWER BARN

7

