Please note that sections with an "*" must be completed or your application can not be processed.

If you need assistance completing the form, please contact Michael Houser, State Architectural Historian, at 360-586-3076 or Michael houser@dahp.wa.gov. Farm Name * Property Location Washington State **HERITAGE BARN** McGourin Farms, Inc. Address: 28101 S. Philleo Lake Road REGISTER City: Spangle Zip: 99031 **Historic Name** County Philleo Barn Spokane * Owners Name * Owner Address Pat & Debbie McGourin Address: Same as above City: State: WA Phone: 509-245-3401 Zip: Email: magooroo@dishmail.net ROOF ROOF FLOOR PLAN **BARN** SIDING **FOUNDATION** PAINTING/ OTHER BARN SHAPE COVERING **MATERIAL** DECORATION **FEATURES** CONDITION ☐ Gable ☐ Asphalt ☐ Square Metal □ Concrete Painted? □ Cupola Metal Rectangular Good Stone □ No Dormer ☐ Wood ☐ Fair ☐ Gothic Round ☐ Wood – Board & ☐ Brick Hav Hood Poor ☐ Irregular ☐ Monitor Other Batten ☐ Wood Color: Red ∇entilator ☐ L- Shape ☐ Wood Vertical ☐ Altered Round ☐ None ☐ Weather Vane Ruins Concrete ☐ Shed ☐ T- Shape ☐ Other Names/Dates/ ☐ Lightning Rod Brick ☐ Conical Size: 40' x 70' Decoration? Silo ☐ Stone ☐ Other * CURRENT USE ⊠ No Milking Shed * BARN **⊠** Ag ☐ Asbestos ☐ Yes ☐ Other ☐ Vacant **BUILT DATE:** Height: 45' to ☐ Other Describe: Other c.1920 peak, 20' at eves * PROPERTY HISTORY: (Expand on the history of the barn/property such as use, builder, architect, family stories and memories, etc., add additional pages if necessary) The nominated barn was built as a replacement barn to a structure that burned down due to loose hay that combusted. The barn housed the horse teams used to farm wheat on the Philleo farm in the northern Palouse region. Horse teams consisted of 4 horses per team, 3 teams, with 3 lead horses. (Total of 15 to pull the combine). All horses were fed and cared for in the main thoroughfare of the barn where three draft horse stalls on each side still exist. This barn is still used to house farm animals, such as 2 horses, 4 steers, 2 goats, 6 ducks, and 2 rabbits. All of these animals are owned by our children and shown at fairs in the 4-H category. It has two stalls in the front, 1 used to house a horse, the other for small animals such as rabbits and ducks. The rear of the barn is open to the pasture and is used for shelter for the steers and goats. The loft is also used to store 60# grass hay bales that are used to feed our animals and also sold to horse owners. 30-40 ton of hay is stored there from time to time. We do not have an exact date of erection of this barn, but our farm has never been sold and has always been handed down to the next generation. We are the fifth generation on the farm.


Please note that sections with an "*" must be completed or your application can not be processed.
If you need assistance completing the form, please contact Michael Houser, State Architectural Historian, at 360-586-3076 or Michael houser@dahp.wa.gov.
Homesteader: Doc Philleo
Son: Edwin Philleo
Granddaughter: Phylliss Philleo (McGourin)
Great Grandson: John M. McGourin
Current Owner & Great Grandson: Patrick McGourin.
The main problem for our harn is that the foundation framing the building has failed. It is a very large issue

* Please provide <u>current</u> photos of nominated property (interior and exterior (all four sides)) and a map indicating the location of property. Digital images are preferred (please provide disc) or print on photographic paper.

OTHER FARMSTEAD BUILDINGS		If building does not exist, please check N/A box * Please provide additional digital photos of secondary buildings/structures							
	ROOF SHAPE	ROOF COVERING	FLOOR PLAN	SIDING	FOUNDATION MATERIAL	OTHER FEATURES: (Color, Trim, etc)	BUILT DATE		
DWELLING ☑ Good ☐ Fair ☐ Poor ☐ Altered ☐ Ruins ☐ N/A	Standard Peak	metal	two level	stucco over brick	stone	white with green trim	1896		
OUTHOUSE Good Fair Poor Altered Ruins N/A							-		
CHICKEN COOP ☐ Good ☐ Fair ☐ Poor ☐ Altered ☐ Ruins ☒ N/A									
MACHINE SHED ☐ Good ☒ Fair ☐ Poor ☐ Altered ☐ Ruins ☐ N/A	Standard Peak	metal		metal	None	Pole style frame, silver metal color	1960		
MILK HOUSE ☐ Good ☐ Fair ☐ Poor ☐ Attered ☐ Ruins ☒ N/A									

Please note that sect	tions with an "*" n	nust be complet	ted or your applic	ation can not be	e processed.						
If you need assistant	ce completing the	form, please co	ontact Michael Ho	ouser, State Arc	hitectural Historian	n, at 360-586-3076 or Michael.house	er@dahp.wa.				
SILO Good Fair Poor Altered Ruins N/A											
OTHER: Shop ☐ Good ☑ Fair ☐ Poor ☐ Altered ☐ Ruins ☐ N/A	Standard Peak	metal		metal	Cement	Pole style frame, silver metal color	1950's				
OTHER: Good Fair Poor Altered Ruins N/A											
Please provide a sketch of the farmstead layout indicating the location of other buildings in relation											
to the barn. Include an arrow pointing north for directional purposes.											

Return form and additional documentation to: DAHP 1063 S. Capitol Way, Suite 106 Olympia, WA 98504






28101 S Philleo Lake Rd Spangle WA 99031-9768 US

Cheney Spangle Road is just to the south of the Barn exactly 1/2 mile

The Philleo BARN





All rights reserved. Use Subject to License/Copyright

This map is informational only. No representation is made or warranty given as to its content. User assumes all risk of use. MapQuest and its suppliers assume no responsibility for any loss or delay resulting from such use.

